

Particle Technology Ltd, Station Yard Industrial Estate, Hatton, Derbyshire, DE65 5DU, United Kingdom Tel: +44(0)1283 520365 www.particletechnology.com



TEST CERTIFICATE

CLIENT: Drhino Ltd

4 Dalton Grove

Bawtry Doncaster DN10 6XS **CERTIFICATE NUMBER**

17980/01 Issue 2

CUSTOMER ORDER NUMBER Tony Fuller

PAGE 1 OF 2

DATE OF RECEIPT

TEST ITEM(S)

03 September 2018

Description	Serial Nº	Model Nº	PTL ID
Drhino Cabinet	D-Type	2301581	25325

TEST SPECIFICATION / ISSUE

DATES OF TEST

TEST(S) APPLIED

BS EN 60529:1992 +A2:2013 IP66 Category 1

Dust 03 September 2018 Water 04 September 2018

Protection Against Solid Foreign Objects, Dust-Tight

Initially all the unit was examined for apertures and openings allowing penetration of a 1mm diameter probe applied with a force of 1N.

Prior to testing the Drhino Cabinet had a vacuum of 19.9 mbar applied to the unit, the airflow rate was measurable at 3.1Lt/min this equated to 1.6vol/hour and therefore required an 8 hour test period. The test conditions were as follows:

Dust Grade: BS EN 60529 Talc Test Dust

Concentration: 2 kg/m³

Duration: 8 hrs

Temperature/Humidity: 21.0 °C / 43% rh

TEST(S) APPLIED

Protection Against Powerful Water Jets

The Drhino Cabinet was placed into the centre of the water test area, it was then allowed to temperature stabilise until the temperature differential between the water and the unit was less than 5°C. The unit was then subjected to water from all practicable directions. The test conditions were as follows:

Flow rate: 100 I/min

Nozzle: IPX6 compliant (12.5 mm)

Duration: 3 minutes

Temperature/Humidity: 17.9°C / 62% rh



Particle Technology Ltd, Station Yard Industrial Estate, Hatton, Derbyshire, DE65 5DU, United Kingdom Tel: +44(0)1283 520365 www.particletechnology.com



TEST CERTIFICATE

CLIENT: Drhino Ltd

4 Dalton Grove

Bawtry Doncaster **DN10 6XS** **CERTIFICATE NUMBER**

17980/01 Issue 2

CUSTOMER ORDER NUMBER Tony Fuller

PAGE 2 OF 2

RESULT(S) OF TEST

There were no apertures or openings on any of the samples permitting entry with a 1mm diameter probe when applying a force of 1N.

On completion of the dust test excess dust was removed by light brushing to allow inspection; no conspicuous damage was noticed on the exterior of the unit.

The Drhino Cabinet was opened for inspection; there was no visible dust ingress into the enclosure.

RESULT(S) OF TEST

IPX6

On completion of the water test excess water was removed before opening the case for inspection. An internal inspection revealed no visible water ingress into the Drhino Cabinet Enclosure.

COMPLIANCE

The Drhino Cabinet conforms to the standard required by BS EN 60529:1992

Date: 05 October 2018

+ A2:2013 IP66 Category 1.

Approved by) **QHS Manager**